



7606 SO. RAMISH STREET, BELL GARDENS, CALIF. 90201 - SP 3-0237

# **VERTICAL MILLING MACHINE**

**MODEL 1/2 V**

## *SERVICE MANUAL*

**READ THIS MANUAL CAREFULLY**

It is essential to give the Serial Number of your machine in any order of repair parts to assure prompt and accurate service.



Order repair parts by part numbers, description and machine serial number.

# VERTICAL MILLING MACHINE

**1 / 2 V**

Table working surface.....	7" × 30"
Longitudinal travel.....	22"
Cross travel.....	7-½"
Vertical travel.....	13-¾"
Spindle travel.....	3-⅛"
Distance spindle to table.....	13-¾"
Distance spindle to column.....	7"
T-Slot, top of table (3).....	9/16"
T-Slot, front of table.....	3/8"
Spindle speeds (9 steps).....	215-3440RPM
Spindle nose.....	R8
Motor.....	1 H.P.
Net weight (approx.).....	964 LBS.
Dimensions of packing case.....	43" × 47" × 61"

## REFERENCE DIMENSIONS:



## FEATURES:

1. Select Model ½ V is a compact vertical milling machine. It is easy to set up. The controls are designed for operator convenience with dual table hand wheels.
2. It is very practical for technical schools, small parts production, toolrooms, R&D work, maintenance shops and even hobby use.
3. The machine is ideally suited for many operations, including: conventional milling, compound angle milling, engraving, drilling and jig boring.
4. All "ways" are hand scraped for perfect bearing and alignment. The table is ground for perfect squareness.
5. Castings are high strength material. They are aged for several months, before normalizing and tempering, to minimize deformation.
6. Anti friction bearings are procured from famous manufacturers such as SKF, FAG, NSK, etc... completely interchangeable world wide.



## —NOTICE—

1. Remove protective crating and skids carefully, in the event of damage in transit, contact our representative and the transportation company making delivery.
2. The machine is carefully inspected and tested in operation by Q.C. personnel before it leaves our factory. If any defects are found on delivery write us directly.
3. Read the catalogue and become familiar with the parts locations on the drawings as it will be easier to understand this operator's manual.

### **I INSTALLATION:**

To set the machine on a solid concrete foundation, it's advisable to apply a little grout to touch up any unevenness in the concrete in order to get a solid foundation at all points.

When setting machine on a floor that has any surface irregularities, shims should be used to correct this condition to the greatest extent possible.

### **II PRE-LUBRICATION:**

Thoroughly clean the machine with gasoline or kerosene, then lubricate all the slide ways with S.A.E. #10 and gears with S.A.E. #30 lubricant. Be sure the machine is lubricated properly before starting.

### **III LEVELLING MACHINES:**

Set machines by levelling the work table lengthwise and crosswise with a precision levelling instrument (refer to the test readings in the attached test records).

### **IV INSPECTION:**

Inspect the machine with the attached original testing records for reference.

### **V SWITCH BOX:**

Switch box is located on the left side of the column, on-off only.

### **VI ADJUSTMENT OF TABLE FEED TRAVEL:**

Table longitudinal and cross feed can be set for any travel distance by adjusting stop set screws that are located in front of table and at the right side of knee.

### **VII ADJUSTMENT OF TABLE GIB:**

The table is provided with a full length tapered gib in the saddle with an adjusting screw on each end. To take up gib tighten the two screws until a slight drag is felt when moving the table by hand. If the table is not tight enough, loosen the adjusting screw on small end, and tighten up adjusting screw on big end. If feel is too tight, reverse the adjusting procedures.

### **VIII ADJUSTMENT OF SADDLE AND KNEE GIBS:**

To tighten gibs the same method as described above is used.

### **IX CLAMPING TABLE, SADDLE AND KNEE:**

When milling with longitudinal table feed only, it is advisable to clamp the knee with the column and the saddle with the knee to add rigidity to these

members and provide for heavier cuts with a minimum of vibration. The saddle locking lever is located on the left side of saddle to the operator, apply clamping pressure properly, as this will hold saddle sufficiently rigid. The table clamping levers are located in front of saddle and should always be clamped when longitudinal movement is not required. The knee clamping lever is at the left side of knee, leave clamped at all times unless the knee is in operation.

#### **X REMOVING TABLE:**

Remove the table as follows : hand wheel, dial holder, bearing bracket, turn the lead screw all the way, so that it can be removed. Complete all the steps then the table can be disassembled easily.

#### **XI REMOVING SADDLE:**

Remove as follows: hand wheel, dial holder, bearing bracket, turn the leadscrew all the way, loosen set screw on the middle of saddle, take off the lead screw nut, and draw saddle gib out. The saddle can then be removed.

#### **XII MOUNTING MOTOR AND SHIFTING BELTS FOR SPEEDS:**

Motor is mounted on a plate hinged to the pulley housing. Release the belt set unit by turning the handle at the side of motor, then shift belts to proper speed as desired, then tighten the belt set unit. A speed change chart is attached inside the pulley cover.

#### **XIII QUILL LOCK AND VERTICAL FEED:**

The handle at the right lower corner of the head is the quill lock. When vertical feed is not in use, set the handle to lock the quill and make the head more stable.

Open the pulley cover to locate a vertical oil cup in front of pulley. Open the cup and drip oil in a couple times a day. This will lubricate all the vertical spindle system from top to bottom.

The micrometer depth stop is graduated in inches. By utilizing these simple graduations, it is possible to work very accurately to different depths. A lock nut under the micrometer nut assures that the micrometer nut is secured properly.

#### **XIV QUILL CLUTCH OF VERTICAL MILLING HEAD:**

The vertical feed ( $\frac{1}{2}V$ ) is controlled by a hand wheel at the front of the head and a handle at the right hand of the head. When hand wheel is in use tighten the clutch lock nut by hand, or loosen it for handle operation. Use hand wheel for fine feeds, handle for fast feeds.

#### **XV VERTICAL HEAD AND TEE ADAPTER:**

Vertical milling head can be tilted 90° on each side by loosening the four locking bolts on tee adapter.

Loosen two set bolts on the adapter, the vertical milling head can then be swivelled 120°; tighten the set bolts after swiveling.

The motor and milling head must tilt together for the motor and head are suspended on the same pulley housing.












1/2 V

## FINAL INSPECTION RECORD

MODEL:

MFG. NO. 64620

DATE: 1977.4

No.	Inspection Items		Illustrations	Tolerances	Measurements
1.	Straightness of upper surface of table			0.03 (0.0012")	0.020
2.	Parallelism of table surface in cross movement			0.02 (0.0008")	0.015
3.	Parallelism of table in longitudinal movement	In table longitudinal travel distance		0.03 (0.0012")	0.020
4.	Perpendicularity of table longitudinal and cross movement			0.02 (0.0008")	0.020
5.	Squareness of movement of main spindle head to upper surface of table	Right and left direction		0.02 (0.0008")	0.010
		Forward and backward direction	 No. lower at the front end of table	0.02 (0.0008")	0.015
6.	Squareness of upper surface of table to center line of main spindle	Right and left direction		0.02 (0.0008")	0.005
		Forward and backward direction	 No lower at the front end of table	0.02 (0.0008")	0.015
7.	Spindle taper hole run-out			0.02 (0.0008")	0.020


Revised and issued by Q C Department

Q C Superintendent

Q C Inspector


C. H. Tseng


Y. L. Day






# PART LOCATION DRAWING









# PART LIST

S/N	P/N	PART NAME	S/N	P/N	PART NAME
1	AIH-1----	Vertical milling head.	36	AIH-33----	Felt ring.
2	AIH-2----	Belt housing cover	37	AIH-34----	Draw bar.
3	AIH-3----	Quill.	38	AIH-35----	Oil tube connector.
4	AIH-4----	Spindle bearing lock nut.	39	AIH-35a----	Oil tube connector.
5	AIH-5----	Lock nut.	40	STD.-----	Oiling cup.
6	AIH-6----	Vertical spindle.	41	STD.-----	Oil tube.
7	AIH-7----	Spindle oil seal.	42	S-40-----	Snap ring.
8	AIH-8----	Bearing adjusting nut.	43	6007-----	Bearing.
9	AIH-9----	Spindle sleeve.	44	STD.-----	Felt.
10	AIH-10----	Pulley locking nut.	45	6206-----	Bearing.
11	AIH-11----	Spindle pulley.	46	R-62-----	Snap ring.
12	AIH-12----	Quill pinion shaft.	47	R-80-----	Snap ring.
13	AIH-13----	Pinion shaft seat.	48	6208-----	Bearing.
14	AIH-14----	Clutch worm gear.	49	51102-----	Thrust bearing.
15	AIH-15----	Clutch.	50	STD.-----	Spring.
16	AIH-16----	Clutch adjusting nut.	51	STD.-----	Spring.
17	AIH-17----	Clutch cover.	52	S-28-----	Snap ring.
18	AIH-18----	Pinion shaft seat.	53	STD.-----	Bolt.
19	AIH-19----	Pinion shaft sleeve.	54	AIH-36----	Swivel arm.
20	AIH-20----	Hand bar holder seat.	55	AIH-37----	Swivel stud.
21	AIH-21----	Handle bar.	56	AIH-38----	Pulley shaft cover.
22	AIH-22----	Worm shaft.	57	AIH-39----	Pulley pivot stud.
23	AIH-23----	Worm shaft sleeve.	58	AIH-40----	Vee belt pulley.
24	AIH-24----	Thrust locking nut.	59	AIH-41----	Motor pulley.
25	AIH-25----	Dial.	60	AIH-42----	Motor mount.
26	AIH-25a----	Dial positioning screw.	61	AIH-43----	Motor suspending pivot.
27	AIH-26----	Hand wheel.	62	AIH-44----	Motor mounting.
28	AIH-27----	Handle.	63	AIH-45----	Motor set unit handle.
29	AIH-28----	Quill locking block.	64	AIH-46----	Belt set unit.
30	AIH-29----	Quill locking bolt.	65	AIH-46a----	Belt set unit.
31	AIH-30----	Quill stop micro screw.	66	AIH-47----	Vertical head adapter.
32	AIH-30a----	Micrometer nut.	67	AIH-48----	Adapter set bolt.
33	AIH-30----	Quill micro stop nut.	68	1/2"-----	Nut.
34	AIH-31----	Quill stopper.	69	B-40-----	Vee belt.
35	AIH-32----	Micrometer scale.	70	5/8"-----	Nut.



# PART LIST

S/N	P/N	PART NAME	S/N	P/N	PART NAME
71	6204	Bearing.	106	AIK	Gear shaft.
72	B-33	Vee belt.	107	AIK-7	Elevating sub dial
73	1HP4 <sup>POLE</sup>	Motor.	108	AIK-8	Elevating handle clutch.
74	AIC-1	Column.	109	AIK-9	Handle arm.
75	AIT-1	Table.	110	AIK-10	Elevating gear.
76	AIT-2	Table gib.	111	AIK-11	Elevating lead screw.
77	AIT-3	Adjusting screw.	112	AIK-12	Elevating lead screw set nut.
78	AIT-4	Longitudinal bearing bracket.	113	AIK-13	Chip guard.
79	AIT-5	Longitudinal lead screw.	114	AIB-1	Base.
80	AIT-6	Lock nut.	115	STD.	Switch.
81	AIT-7	Longitudinal feed nut.	116	$\frac{3}{8}'' \times 2''$	Bolt.
82	AIT-8	Washer.	117	STD.	Light.
83	AIT-9	Dial.	118	STD.	Rubber sheet.
84	AIT-9a	Dial positioning screw.	119	STD.	Bolt.
85	AIT-10	Hand wheel.	120	6204	Bearing.
86	AIT-11	Handle bar.	121	$\frac{3}{8}''$	Nut.
87	AIT-12	Long. travel adjusting screw.	122	STD.	Spring lock washer.
88	AIT-12a	Adjusting screw sleeve.	123	$\frac{1}{4}'' \times \frac{3}{4}''$	Bolt.
89	AIT-13	Table stopper.	124	$\frac{1}{4}''$ DIA.	Copper block.
90	AIT-14	Table locking screw.	125	6303	Bearing.
91	AIT-15	Handle bar.	126	S-17	Snap ring.
92	AIS-1	Saddle.	127	STD.	Oil cup.
93	AIS-2	Saddle gib.	128	STD.	Bolt.
94	AIS-3	Chip guard.	129	STD.	Bolt.
95	AIS-4	Cross lead screw.	130	STD.	Grease nipple.
96	AIS-5	Cross feed nut.	131	$\frac{3}{8}''$ DIA.	Copper block.
97	AIS-6	Cross feed bearing bracket.	132	S-18	Snap ring.
98	AIS-7	Stop block.	133	STD.	Nut.
99	AIS-8	Stop block fixture.	134	STD.	Copper block.
100	AIS-9	Cross travel adjusting screw.	135	STD.	Nut.
101	AIS-9a	Adjusting screw sleeve.	136	STD.	Bolt.
102	AIK-1	Knee.	CAUTION: Find the serial number from the drawing, then use it to obtain the part number from this list.		
103	AIK-2	Knee gib.			
104	AIK-3	Table locking screw.			
105	AIK-5	Gear shaft sleeve.			