



nMotion CNC Controller




nMotion CNC Controller

24V+
EGND
EGND
E5V+
E5V+
PWM
SP+
SP-
016
015
014
013
012
011
010
09
DGND
DCOM

079
0V
081
085
083
0V
+24





055

077

075

071

690

065

063

059

057



110V

Before power on please check
input voltage avoiding damage

2A 2B 2C 2D 2E 2F 2G 2H 2I 2J 2K 2L

09
DCOM
DGND

5V+
DGND